



FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM	
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

COUNTY: Currituck

PERMIT NO.: SLAS-27-11

FILE TYPE: COMPLIANCE

Date of Site Inspection: 7-23-12

FACILITY NAME AND ADDRESS:

Hoffman Septic Tank Pumping
110 Enterprise Dr.
Elizabeth City, NC 27909

GPS COORDINATES: N: 36.37103° W: -75.99829°

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Paul Hoffman
Telephone: 252-339-4900
Email address:
Fax:

FACILITY CONTACT ADDRESS:

1157 Shawboro Rd
Shawboro, NC 27973

PARTICIPANTS:

Will Burke, Environmental Senior Specialist

STATUS OF PERMIT:

Active

PURPOSE OF SITE VISIT:

Routine, Audit

OBSERVED VIOLATIONS

1. n/a

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Access road was in good shape.
2. No serious vectors or odors noted during this inspection.
3. Crop appears to be in good condition.
4. Field border markers are up and easy to identify.
5. Required signage is up and easy to read.
6. Applications appear to have been performed in a professional and responsible manner.

Please contact me if you have any questions or concerns regarding this inspection report.



Will Burke
Regional Representative

Phone: (910) 796-7397

Sent on: 8-20-12		Email		Hand delivery	X	US Mail		Certified No. <u> </u>
------------------	--	-------	--	---------------	---	---------	--	-------------------------